

MAR 23 1990

BOEING**SECURITY FIRE PROTECTION INCIDENT REPORT**

TIME OUT 12:26 pm	TIME IN 16:51 pm	TIME OF INCIDENT 12:26 pm	NO. OF MEN 8	REPORT NO. R0-0095
----------------------	---------------------	------------------------------	-----------------	-----------------------

DATE 3-18-90	DAY Sunday	SHIFT First	PLANT Renton	BUILDING 4-01	FLOOR Door 19	COLUMN
ORG. NO.	ORG. NAME	SUPERVISOR			PHONE	

NATURE OF INCIDENT:

HAZARDOUS CONDITION: Engine 20 responded to building 4-01, inside door 19, on a reported bulging drum. A check of the area confirmed a 55 gallon drum on a pallet, with the identification Penetone De-icer 809, was involved. There were no MSDS available for the product so

CAUSE OF INCIDENT:

contact was made with Boeing Haz-Mat personnel for assistance. Due to the unknown content of the drum, extreme caution was recommended by the Industrial Hygienist and Safety representative. Renton Fire Department Haz-Mat Team was requested for assistance. Renton Fire

CORRECTIVE ACTION/SERVICE:

personnel entered the area with SCBA and bunkers to clear a path for a forklift to remove the pallet. A Boeing Haz-Mat member, with SCBA and Level B protection, used a forklift to remove the pallet from the building. Boeing Firefighters manned a Dry Chemical wheel cart (over)

TYPE OF INJURIES SUSTAINED:

FIRE LOSSES	VALUE OF PROPERTY	PER:
PRODUCTION MANHOURS		PER:

EQUIPMENT USED:	Engine 20	EXTNG AGENT
-----------------	-----------	-------------

FIRE PERSONNEL	Lt. D. Cook, Lt. J. Francisco, D. Brassard, K. Spohn, S. Gerard, F. Sinclair, G. Reinke, J. Buttler, D. Nelson
----------------	--

FIRE BRIGADE PERSONNEL	
MUTUAL AID COS. RESPONDING EQUIPMENT	Renton Fire Department Haz-Mat Team

HOW WAS ALARM RECEIVED?	<input type="checkbox"/> ADT	<input checked="" type="checkbox"/> BUSINESS PHONE	<input type="checkbox"/> GUARD	<input type="checkbox"/> VERBAL	<input type="checkbox"/> RADIO
-------------------------	------------------------------	--	--------------------------------	---------------------------------	--------------------------------

DISCOVERED BY	EMP. NAME Richard Paneaude	CLOCK NO. 7566	ORG. R-6210	PHONE 237-9900
---------------	-------------------------------	-------------------	----------------	-------------------

REPORTED BY	- SAME -	CLOCK NO.	ORG.
-------------	----------	-----------	------

A.D.T. ALARM (TYPE)	TIME	RESET
---------------------	------	-------

NO. OF SPRINKLER HEADS FUSED	NO. OF RISERS AFFECTED	CLOSED: FROM	TO
------------------------------	------------------------	--------------	----

FOLLOW-UP INVESTIGATION	<input type="checkbox"/> YES	<input type="checkbox"/> NO	FOLLOW-UP
-------------------------	------------------------------	-----------------------------	-----------

RECOMMENDATIONS

DATE 3-18-90	SIGNATURE D. Cook	TITLE Lieutenant	PHONE 237-2888
-----------------	----------------------	---------------------	-------------------

RO-0095 continued

- in case of fire with Renton Firefighters on a backup hose line. The pallet was brought outside and placed into a containment pallet. A piercing unit was placed on top of the bulging drum and was remotely operated to make a hole in the top of the container. The barrel was pierced with no complications and was taken to the waste storage area for disposal. There were no personnel evacuated due to the area unoccupied on Sunday and there were no injuries.

Personnel at the scene:

Ted Frees - Facilities
Yvette Barnett - Environmental
Al Rossner - Industrial Hygiene
Kevin Jacobson - Safety
Rick Pateneau - Maintenance
Gary Gotti - Renton Fire Battalion Chief

Notifications

. Johnston - Fire Chief
R. Selter - S&FP Sr. Manager
C. Morris - S&FP Director
C. Kalkstine - Security Captain
J. Gamble - Public Relations